



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55175

Inspection Report

Project Name: 5393 Chiswick Circle ~ COBI

Address: 5393 Chiswick Circle ~ COBI ,Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1500590.0000

Scope of Inspection: Final Mechanical Inspection

Inspection Type: See Scope

Date: 08/05/2015 Any am

Permit No: 2015-07-045

Lot No.:

Contact: Renee at 407-282-6885

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/05/2015	label not marked with unit type or amp size	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362