



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55210

## Inspection Report

Project Name: 5903 Randolph Avenue ~ COBI (commercial)

Date: 08/05/2015 Any pm

Address: 5903 Randolph Avenue ~ COBI (commercial) ,Belle Isle,  
Orange County, FL

Permit No: 2015-06-050

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400382.0000

Contact: Manuel Umpierre at 407-947-8835

Scope of Inspection: Final Building Inspection for storefront security doors

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489