



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55245

Inspection Report

Project Name: 5903 Randolph Avenue ~ COBI (commercial)

Address: 5903 Randolph Avenue ~ COBI (commercial) ,Belle Isle,
Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400382.0000

Scope of Inspection: Fire Sprinkler Inspection

Inspection Type: See Scope

Date: 08/06/2015 Any am

Permit No: 2015-07-032

Lot No.:

Contact: Eddie Miller, Jr. at 407-467-9776

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/06/2015	visual for 1st and 3rd floors	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362