



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55317

## Inspection Report

Project Name: 5903 Randolph Avenue ~ COBI (commercial)  
Address: 5903 Randolph Avenue ~ COBI (commercial) ,Belle Isle,  
Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400382.0000  
Scope of Inspection: Above Ceiling Fire Caulking Inspection  
Inspection Type: See Scope

Date: 08/07/2015 03:00 pm  
Permit No: 2015-07-015  
Lot No.:  
Contact: Mac at 407-223-9063

Disposition of Inspection: Pass

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489