



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55316

Inspection Report

Project Name: 5903 Randolph Avenue ~ COBI (commercial)

Address: 5903 Randolph Avenue ~ COBI (commercial) ,Belle Isle,
Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1400382.0000

Scope of Inspection: Above Ceiling Final Building Inspection

Inspection Type: See Scope

Date: 08/07/2015 03:00 pm

Permit No: 2015-07-015

Lot No.:

Contact: Mac at 407-223-9063

Disposition of Inspection: Partial Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/08/2015	Approved to install ceiling tiles to install fixtures.	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489