



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55033

Inspection Report

Project Name: 5903 Randolph Avenue ~ COBI (commercial)

Date: 07/31/2015 Early am

Address: 5903 Randolph Avenue ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-08-004

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400381.0000

Contact: Mac at 407-223-9063

Scope of Inspection: Rough electrical inspection

Inspection Type: See Scope

Disposition of Inspection: Partial Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
07/31/2015	Electrical Below Ceiling Rough. Still needs above ceiling.	Donald Beckman

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Donald Beckman, BN5123