



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55078

Inspection Report

Project Name: 5933 Randolph Avenue ~ COBI (commercial)

Date: 08/03/2015 Any am

Address: 5933 Randolph Avenue ~ COBI (commercial) ,Belle Isle,
Orange County, FL

Permit No: tbd

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1400382.0000

Contact: Mac or George at 863 860 8919

Scope of Inspection: Mechanical fire damper inspection

Inspection Type: See Scope

Disposition of Inspection: Partial Pass

Comments:

Task Date

Task Note

User Name

08/03/2015

fire dampers 3rd floor

Thomas Romboli

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Thomas Romboli, BN 3493