



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55675

## Inspection Report

Project Name: 6521 St. Partin Place ~ COBI

Date: 08/14/2015 Any am

Address: 6521 St. Partin Place ~ COBI ,Belle Isle, Orange County, FL

Permit No: 2015-08-003

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501047.0000

Contact: Leslie Tischler at 407-273-0078

Scope of Inspection: Final Building Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Thomas Romboli, BN 3493