



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 55725

## Inspection Report

Project Name: 6633 St. Partin Place ~ COBI  
Address: 6633 St. Partin Place ~ COBI ,Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1400097.0000

Date: 08/17/2015 Any any  
Permit No: 2015-07-039  
Lot No.:  
Contact: Indira Gonzalez-Rosas at 407-809-5311

Scope of Inspection: In-Progress Window Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/17/2015	in progress window inspection	Ralph Jones

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Ralph Jones, BN1437