UNIVERSAL
ENGINEERING SCIENCES
Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review
3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 56410

Inspection Report

Project Name:	2845 Montmart Drive ~ COBI	Date:	08/28/2015 Any any
Address:	6669 Franconia Drive ,Belle Isle, Orange County, FL 32812	Permit No:	2015-08-039
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1501117.0000	Contact:	John at 407-925-6193
Scope of Inspection:	Roof Deck Nailing/Dry-in/Flashing Inspection		
Inspection Type:	**See Scope**		

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362