

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70739

Inspection Report

Project Name: 1416 Wilkes Avenue ~ COBI	Date:	08/09/2016 Late am	
Address: 1416 Wilkes Avenue ~ COBI, Belle Isle, Orange County, FL	Permit No:	2016-07-004	
Client: City of Belle Isle	Lot No.:		
ProjectNo.: 0115.1600380.0000-0115-01	Contact:	Stephanie Williams at 321.303.2958	
Scope of Inspection: Roof Dry-in Inspection			
Inspection Type: See Scope			
Disposition of Inspection: Pass			

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489

W. Z. Moody