



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70806

Inspection Report

Project Name: 1424 Swann Avenue ~ COBI

Date: 08/11/2016 Any any

Address: 1424 Swann Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-04-045

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600279.0000-0115-03

Contact: David Rivera at 321-946-7223

Scope of Inspection: Final Roof Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362