



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70804

Inspection Report

Project Name: 1527 Idaho Avenue ~ COBI

Date: 08/15/2016 Early pm

Address: 1527 Idaho Avenue ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-07-031

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600403.0000-0115-01

Contact: Indira Gonzalez-Rosas at 407-809-5311

Scope of Inspection: In-Progress Door Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362