



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71514

Inspection Report

Project Name: 1601 DeWayne Drive ~ COBI

Date: 08/30/2016 Any pm

Address: 1601 DeWayne Drive ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-07-034

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600405.0000-0115-01

Contact: Marisol Mojica at 407-261-2277

Scope of Inspection: In-progress Window Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362