



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71389

Inspection Report

Project Name: 1646 Wind Willow Road ~ COBI

Date: 08/25/2016 Any any

Address: 1646 Wind Willow Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-03-021

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600196.0000-0115-01

Contact: Jeanne Gallagher at 407-413-3627

Scope of Inspection: Final Electrical Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/25/2016	NEC 210 Exposed live parts	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362