



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71180

## Inspection Report

Project Name: 1700 Nela Avenue ~ COBI

Date: 08/23/2016 Any am

Address: 5238 Jade Circle ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-07-033

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600404.0000-0115-01

Contact: Susan Manchester at 407 581  
8161

Scope of Inspection: Investigate screen enclosure work without a permit. If evidence is present, post SWO & email picture to COBIpermits.

Inspection Type: See Scope

Disposition of Inspection: Complete

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/23/2016	Investigate screen enclosure work without a permit at this address and found no signs of any such work present.	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466