



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71069

Inspection Report

Project Name: 1705 Wind Harbor Road ~ COBI

Date: 08/18/2016 Any am

Address: 1705 Wind Harbor Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-03-007

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600174.0000-0115-01

Contact: Mark Jensen at 407-947-9982

Scope of Inspection: Final Building Inspection for master bedroom/bathroom addition

Inspection Type: **Building - Final**

Disposition of Inspection: **Pass**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/18/2016	Building Final Inspections for Master Bedroom/Bathroom Addition	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466