



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71071

Inspection Report

Project Name: 1705 Wind Harbor Road ~ COBI

Date: 08/18/2016 Any am

Address: 1705 Wind Harbor Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-03-053

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600174.0000-0115-02

Contact: Mark Jensen at 407-947-9982

Scope of Inspection: Final Plumbing Inspection for master bathroom addition

Inspection Type: **Plumbing - Final**

Disposition of Inspection: **Pass**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/18/2016	Final Plumbing Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466