



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70616

Inspection Report

Project Name: 1723 Wind Drift Road ~ COBI
Address: 1723 Wind Drift Road ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1600424.0000-0115-01

Date: 08/05/2016 Any any
Permit No: 2016-07-044
Lot No.:
Contact: Samantha Schmidt at 407-250-6768

Scope of Inspection: In-Progress Window Inspection

Inspection Type: **Buidling Insulation**

Disposition of Inspection: **Fail**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/05/2016	In-Progress Window Buck Inspection failed due to no access to work provided. No one at home. Called Samatha Schmidt and left voice mail.	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466