



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70759

Inspection Report

Project Name: 1723 Wind Drift Road ~ COBI

Date: 08/11/2016 Any any

Address: 1723 Wind Drift Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-07-044

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600424.0000-0115-01

Contact: Samantha Schmidt at 407-440-2874

Scope of Inspection: In-Progress Window ReInspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362