



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71089

Inspection Report

Project Name: 1723 Wind Drift Road ~ COBI

Date: 08/19/2016 Any pm

Address: 1723 Wind Drift Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-07-044

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600424.0000-0115-01

Contact: Samantha Schmidt at 407-250-6768

Scope of Inspection: Final Building Inspection for Windows

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/19/2016	Final Building Inspection for Windows	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466