



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70853

Inspection Report

Project Name:	1812 Wind Willow Road ~ COBI	Date:	08/12/2016 Any any
Address:	1812 Wind Willow Road ~ COBI, Belle Isle, Orange County, FL	Permit No:	2016-08-015
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1600442.0000-0915-01	Contact:	Susan Manchester at 407 581 8161
Scope of Inspection:	REVIEW mechanical permit app for one, 3-ton change out		
Inspection Type:	See Scope		

Disposition of Inspection: Complete

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/15/2016	<p>From: Art Barthlow Sent: Friday, August 12, 2016 5:58 AM To: Susan Manchester Subject: RE: 1812 Wind Willow Road - review for mechanical permit 2016-08-015 - No Sweat AC & Heat LLC</p> <p>Susan, Its fine let's go with it.</p> <p>Best Regards, Art Barthlow, Senior Plans Examiner CBC, BN, PX, CFI, BU, MCP</p>	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Susan Manchester