



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70325

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring Suites

Date: 07/29/2016 Any am

Address: 1934 McCoy Road ~ COBI commercial, Belle Isle, Orange County, FL

Permit No: 2016-04-016

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501343.0000-0115-06

Contact: Rick Weeks at 863-236-1110

Scope of Inspection: Tub Set Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
07/29/2016	2nd Floor tub/shower set all but 3 H/C Rooms and 1 Regular Room	David Young
	3rd Floor Tub/Shower set all but the two H/C Rooms	

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466