



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70560

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring Suites

Date: 08/04/2016 Any am

Address: 1934 McCoy Road ~ COBI commercial, Belle Isle, Orange County, FL

Permit No: 2016-05-014

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501343.0000-0115-08

Contact: John at 941-705-4558

Scope of Inspection: Fire Inspection - Hydro Test Inspection for the sprinklers

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/04/2016	Gauge remained constant at 235 psi for 2 hours	Lisa Whaley

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Fire Prevention Code.

Inspector: Lisa Whaley, 153187