



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70957

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring Suites

Address: 1934 McCoy Road ~ COBI commercial, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501343.0000-0115-12

Date: 08/17/2016 Any any

Permit No: 2016-08-018

Lot No.:

Contact: Susan Manchester at 407 581 8161

Scope of Inspection: REVIEW building app for hotel signage

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927