



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71297

Inspection Report

Project Name: 1934 McCoy Road ~ COBI commercial ~ Woodspring Suites

Date: 08/23/2016 Any am

Address: 1934 McCoy Road ~ COBI commercial, Belle Isle, Orange County, FL

Permit No: 2016-10-065

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1501343.0000-0115-01

Contact: Richard Coody at 229-886-5550

Scope of Inspection: Insulation Inspection

Inspection Type: **See Scope**

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498