



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70343

Inspection Report

Project Name: 2112 Belle Isle Avenue ~ COBI

Address: 2112 Belle Isle Avenue ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600349.0000-0115-02

Scope of Inspection: Final Roof Inspection

Inspection Type: Roofing - Final

Date: 07/29/2016 Any am

Permit No: 2016-06-025

Lot No.:

Contact: Lesley Bartoe at 407-656-1470

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
07/29/2016	Roofing Final on Dock Roof	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466