



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70750

Inspection Report

Project Name: 2112 Belle Isle Avenue ~ COBI

Date: 08/10/2016 Any any

Address: 2112 Belle Isle Avenue ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-07-046

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600349.0000-0115-03

Contact: Robert Byrd at 407 405 5753

Scope of Inspection: Final Electrical Inspection

Inspection Type: **Electrical - Final**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706