



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70817

Inspection Report

Project Name: 2112 Belle Isle Avenue ~ COBI

Date: 08/12/2016 Any any

Address: 2112 Belle Isle Avenue ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-06-024

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600349.0000-0115-01

Contact: Lesley Bartoe at 407-656-1470

Scope of Inspection: Final Building Inspection for Boat Dock

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489