



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70608

Inspection Report

Project Name: 2320 Homewood Drive ~ COBI

Address: 2320 Homewood Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1501541.0000-0115-03

Scope of Inspection: Final T-Pole Inspection

Inspection Type: See Scope

Date: 08/05/2016 Any any

Permit No: 2016-08-006

Lot No.:

Contact: Clarence Tibbs at 407-509-2733

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/05/2016	T-Pole Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466