



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70695

Inspection Report

Project Name: 2830 Nela Avenue ~ COBI	Date: 08/09/2016 Any any
Address: 2830 Nela Avenue ~ COBI, Belle Isle, Orange County, FL	Permit No: 2016-07-021
Client: City of Belle Isle	Lot No.:
ProjectNo.: 0115.1600391.0000-0115-01	Contact: Jessica Graf at 407-851-0680
Scope of Inspection: Roof Covering In-progress Inspection	
Inspection Type: See Scope	

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/09/2016	Not ready for Inspection...FBC 110.5	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489