



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70693

Inspection Report

Project Name: 2830 Nela Avenue ~ COBI

Address: 2830 Nela Avenue ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600391.0000-0115-01

Scope of Inspection: Roof Dry-in/Flashing/Deck Nailing Inspection

Inspection Type: See Scope

Date: 08/09/2016 Any any

Permit No: 2016-07-021

Lot No.:

Contact: Jessica Graf at 407-851-0680

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/09/2016	Not ready for Inspection ...FBC 110.5	William Moody

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489