



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70834

Inspection Report

Project Name: 2909 Flowertree Road ~ COBI

Date: 08/12/2016 Any any

Address: 2909 Flowertree Road ~ COBI, Belle Isle, Orange County, FL

Permit No: 2016-06-023

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600350.0000-0115-03

Contact: Shawn Fred at 407-366-4600

Scope of Inspection: Equipotential Bond Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/15/2016	From: William Moody Sent: Monday, August 15, 2016 8:06 AM To: Collina Gast Subject: RE: 2909 Flowertree Rd (COBI) Equipotential bond / Deck inspection approved.	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: William Moody, BN4489