



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71444

Inspection Report

Project Name: 2909 Flowertree Road ~ COBI

Address: 2909 Flowertree Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600350.0000-0115-01

Scope of Inspection: Pool Safety Inspection

Inspection Type: See Scope

Date: 08/26/2016 Any any

Permit No: 2016-06-021

Lot No.:

Contact: Martin at 407-421-1188

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/26/2016	No One Home.... Knock On Door Rang Door Bell Was Greeted by Large Dog Barking At Front Door No Access...No Inspection Performed	Karl McGuire
08/29/2016	Per Karl: FBC 110.5	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498