



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71515

Inspection Report

Project Name: 2909 Flowertree Road ~ COBI

Address: 2909 Flowertree Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600350.0000-0115-01

Scope of Inspection: Pool Safety ReInspection

Inspection Type: **See Scope**

Date: 08/29/2016 Any pm

Permit No: 2016-06-021

Lot No.:

Contact: Shawn Fred at 407-366-4600

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/29/2016	Pool Safety Re-Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466