



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70888

## Inspection Report

Project Name: 3001 Flowertree Road ~ COBI

Address: 3001 Flowertree Road ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600364.0000-0115-01

Scope of Inspection: Final Building Inspection for Shed

Inspection Type: See Scope

Date: 08/15/2016 Any am

Permit No: 2016-06-047

Lot No.:

Contact: Linda Steinard at 407-251-8639

Disposition of Inspection: Fail

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/15/2016	FBC R 110.5 Work not ready electric final required to pass prior to building final	Luis Colon

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Luis Colon, BN3362