



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71109

## Inspection Report

Project Name: 3001 Flowertree Road ~ COBI  
Address: 3001 Flowertree Road ~ COBI, Belle Isle, Orange County, FL  
Client: City of Belle Isle  
ProjectNo.: 0115.1600364.0000-0115-01

Date: 08/19/2016 Any any  
Permit No: 2016-06-047  
Lot No.:  
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: Final building inspection for shed

Inspection Type: See Scope

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/19/2016	Final Building Inspection for Shed	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466