



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70856

Inspection Report

Project Name: 3520 Country Lakes Drive ~ COBI

Address: 3520 Country Lakes Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600268.0000-0115-03

Scope of Inspection: Final Building Inspection for Windows and Doors

Inspection Type: See Scope

Date: 08/12/2016 Any am

Permit No: 2016-05-008

Lot No.:

Contact: Gregg Necrason at 407 758-5889

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/12/2016	Final Building Inspection for windows and doors.	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466