



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70855

Inspection Report

Project Name: 3520 Country Lakes Drive ~ COBI

Date: 08/12/2016 Any am

Address: 3520 Country Lakes Drive ~ COBI, Belle Isle, Orange
County, FL

Permit No: 2016-05-058

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600268.0000-0115-08

Contact: Gregg Necrason at 407 758-5889

Scope of Inspection: Final Electrical Inspection

Inspection Type: See Scope

Disposition of Inspection: Fail

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/12/2016	Final Electrical Inspection Failed FBC-B 110.5 Work not complete Florida Room has two electrical boxes in the ceiling with exposed wiring. Dining Room has one electrical box in the ceiling with exposed wiring.	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466