



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71134

## Inspection Report

Project Name: 3520 Country Lakes Drive ~ COBI

Address: 3520 Country Lakes Drive ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600268.0000-0115-08

Scope of Inspection: Final Electrical Re-Inspection

**Inspection Type: See Scope**

Date: 08/19/2016 Any pm

Permit No: 2016-05-058

Lot No.:

Contact: Gregg Necrason at 407 758-5889

**Disposition of Inspection: Pass**

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/19/2016	Final Electrical Re-Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466