

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70603

Inspection Report

Project Name: 3654 Rothbury Dr ~ COBI

Address: 3654 Rothbury Dr ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600414.0000-0115-02

Seepe of Improstion: Final Plumbing Improstion

Scope of Inspection: Final Plumbing Inspection

Inspection Type: Plumbing - Final

Disposition of Inspection: Pass

Comments:

Task DateTask NoteUser Name08/04/2016Final Plumbing InspectionDavid Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466