

### 3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

#### Work Order No. 70935

# **Inspection Report**

Inspection Type:		See Scope		
Scope of Inspection:		REVIEW plumbing permit app to change-out toilet, tub & sink		
ProjectNo.: 0115.		1600446.0000-0115-01	Contact:	Susan Manchester at 407 587 8161
Client:	City of Bell	lle Isle Lot No.:		
Address:	3727 Saint FL	Moritz Street ~ COBI, Belle Isle, Orange County,	Permit No:	2016-08-021
Project Name: 3727 Saint Moritz Street ~ COBI			Date:	08/15/2016 Any any

## Disposition of Inspection: Complete

## **Comments:**

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector:

Dale Baker, BN 3927

Jole Baker