



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71393

Inspection Report

Project Name:	3727 Saint Moritz Street ~ COBI	Date:	08/26/2016 Any am
Address:	3727 Saint Moritz Street ~ COBI, Belle Isle, Orange County, FL	Permit No:	2016-08-021
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1600446.0000-0115-01	Contact:	Harvey Baker at 407-453-8292
Scope of Inspection:	Rough Plumbing Inspection		
Inspection Type:	See Scope		

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/26/2016	Rough Plumbing Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466