



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71466

## Inspection Report

Project Name:	3727 Saint Moritz Street ~ COBI	Date:	08/26/2016 Any any
Address:	3727 Saint Moritz Street ~ COBI, Belle Isle, Orange County, FL	Permit No:	2016-08-036
Client:	City of Belle Isle	Lot No.:	
ProjectNo.:	0115.1600446.0000-0115-02	Contact:	Susan Manchester at 407 581 8161
Scope of Inspection:	REVIEW app for electrical work		
Inspection Type:	See Scope		

Disposition of Inspection: Pass

### Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/26/2016	Review Residential Electrical Application	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466