



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70323

Inspection Report

Project Name: 4226 Belle Grove Court ~ COBI

Address: 4226 Belle Grove Court ~ COBI, Belle Isle, Orange County, FL

Client: City of Belle Isle

ProjectNo.: 0115.1600343.0000-0115-03

Scope of Inspection: Rough Electrical Inspection

Inspection Type: **Electrical - Rough In**

Date: 07/29/2016 Any am

Permit No: 2016-06-007

Lot No.:

Contact: Aleksandar Hrkalovic at 407-690-9334

Disposition of Inspection: Pass

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
07/29/2016	Electrical Rough-In Inspection	David Young

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: David Young, BN466