



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70640

Inspection Report

Project Name: 4226 Belle Grove Court ~ COBI

Date: 08/09/2016 Any any

Address: 4226 Belle Grove Court ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-06-005

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600343.0000-0915-01

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW revision to building plans - adding wood fired pizza oven to covered porch (has roof but no
walls - open)

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Susan Manchester