



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70926

Inspection Report

Project Name: 4254 Cranmore Court ~ COBI
Address: 4254 Cranmore Court ~ COBI, Belle Isle, Orange County, FL
Client: City of Belle Isle
ProjectNo.: 0115.1600445.0000-0115-01

Date: 08/16/2016 Any any
Permit No: 2016-08-020
Lot No.:
Contact: Susan Manchester at 407 581 8161

Scope of Inspection: Final building inspection for pool (to close-out old Orange County permit B01003242)

Inspection Type: **Building - Final**

Disposition of Inspection: **Fail**

Comments:

<u>Task Date</u>	<u>Task Note</u>	<u>User Name</u>
08/17/2016	Per Jim: no bonding to the screen & the mechanicals. NEC 680.26b5	Collina Gast

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: James Pappalardo, BN5706