



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70961

Inspection Report

Project Name: 5025 Saint Denis Court ~ COBI

Date: 08/16/2016 Any any

Address: 5025 Saint Denis Court ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-08-022

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600448.0000-0115-01

Contact: Susan Manchester at 407 581
8161

Scope of Inspection: REVIEW building app for interior remodel

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Dale Baker, BN 3927