



UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences
Geophysical Services • Materials Testing • Threshold Inspection
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 71313

Inspection Report

Project Name: 5025 Saint Denis Court ~ COBI

Date: 08/23/2016 Any any

Address: 5025 Saint Denis Court ~ COBI, Belle Isle, Orange County,
FL

Permit No: 2016-08-017

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600448.0000-0115-03

Contact: Troy Ruckman at 407-341-0237

Scope of Inspection: Rough Plumbing Inspection

Inspection Type: See Scope

Disposition of Inspection: Pass

Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Building Code.

Inspector: Karl McGuire, BN5498