



# UNIVERSAL ENGINEERING SCIENCES

Consultants In: Geotechnical Engineering • Environmental Sciences  
Geophysical Services • Materials Testing • Threshold Inspection  
Building Code Administration, Compliance Inspection & Plan Review

3532 Maggie Blvd, Orlando, FL 32811 - P: 407.423.0504 - F: 407.423.3106

Work Order No. 70377

## Inspection Report

Project Name: 5174 S. Conway Road ~ COBI commercial unit 5174 of  
5120 Conway Road Shopping Center - Chai Thia  
Restaurant

Date: 07/29/2016 11:00 am

Address: 5174 S. Conway Road ~ COBI commercial, Belle Isle,  
Orange County, FL

Permit No: 2016-06-053

Client: City of Belle Isle

Lot No.:

ProjectNo.: 0115.1600216.0000-0115-06

Contact: David Rose Jr. at 321-354-5666

Scope of Inspection: Fire Inspection - Fire Sprinkler Overhead Visual Inspection

Inspection Type: **See Scope**

Disposition of Inspection: **Pass**

### Comments:

I hereby affirm that to the best of my knowledge and belief, the above listed inspection was performed as indicated and the work was reviewed for compliance with the approved plans, and all pertinent sections of the Florida Fire Prevention Code.

Inspector: Lisa Whaley, 153187